

- MUST BE CHECKED 8-ALL FIELD MEASUREMENTS TAKEN FOR THIS SURVEY WERE MADE WITH ELECTRONIC TRANSIT AND/OR STEEL TAPE W/ACCU. 1:7500 9-THIS SURVEY IS FOR USE AS PER REQUEST AND NOT FOR ANY OTHER PURPOSE. 10- THIS SURVEY WAS PREPARED WITHOUT THE BENEFIT OF A COMMITMENTS FOR TITLE INSURANCE 11- DATE OF FIELD WORK 05/13/2009
- DATE OF FIELD WORK 05/13/2009

ELECTFILE CODE #2300COLUMBIA71209 Survey is not valid without the signature and raised/digital seal of the Florida Registered Professional Land Surveyor and Mapper The boundary survey of the property shown hereon is in accordance with the description furnished by the client. No search of public records has been made by this office for accuracy or omissions. Subject to opinion title and any dedications, limitations, restrictions or easements of record. No underground improvements and/or utilities were located

NOTE:

OOD DATA PROVIDED IS FOR THE FLOOD DATA PROVIDED IS FOR INFORMATION PURPOSES ONLY. THE SURVEYOR MAKES NO GUARANTEES AS TO THE ACCURACY OF THE INFORMATION PROVIDED THE LOCAL F.E.M.A. AGENCY SHOULD BE CONTACTED FOR VERIFICATION

BASIS OF BEARING BASE: BEARING BASE SHOWN HEREON ARE BASED ON NORTHEASTERLY LINE OF LOT 5 BLOCK-39, BEING N 51°17'08" E PER PLAT HECTOR LEBRON

PROFESSIONAL SURVEYOR AND MAPPER

LB7619

05-19-2009

I Hereby Certify: That the attached boundary survey of the property described below is to the best of my knowledge and belief accurate as recently surveyed under my direction; also that there are no above ground encroachments other than those shown, and that this survey meets the minimum technical standards set by the Florida Board of Land Surveyors as set forth in Section 472.027 (F.S.) Chapter 61G17-6 of The Florida Aministrative Code.